

PS NAME "ATHOS 11" REPORT Ant. No. 37445

standing Conditions of Class: SUBJECT to bulged fore peak bulkhead, buckled No.1 forward middle line bulkhead and set up keel plates Nos. 1 & 2 also shell plates A.3 (p & s.f.) and to after peak tank top slightly wavy being specially examined and dealt with as necessary and to wasted reverse frame in No.5 hold (s.s.) and indented upper deck plating abreast tonnage hatchway (p.s.) being examined and dealt with as necessary, by the Special Survey.

L. Appendix. (~~As before~~ or None)

ays due: A SPECIAL SURVEY (C) became due 7,61 but postponement until 7,62 was approved 24.5.61.

ce of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs on account of damage stated due to striking quay wall. Equipment - a bower anchor now supplied and verified - 30 fms. of c.c. lost.

al Features:

Interim Certificate in order (Yes-~~No~~-None)

s Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: 7,62.

omendation:

SUBJECT as above, and to indented and torn shell plating (p.s.) in way of forecastle being examined and dealt with as necessary by the Special Survey also to 30 fathoms of chain cable being supplied at the earliest opportunity, but ACTION be DEFERRED for a Special Survey.

SUBJECT



© 2020

Lloyd's Register Foundation

002592-02601-0246