

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Motor Tanker "EMPIRE INDUSTRY" REPORT Bel. No. 13590

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15640Depth "d" -2nd Long. No. 42780Proportions = $\frac{L}{D}$ 13.52Framing As approvedSheerstrake As approvedTwo longitudinal bulkheads are fitted.

This is a sister vessel to the "DERWENTDALE", "EMPIRE DIAMOND",
"DINSDALE", "EMPIRE CHAPMAN", "EMPIRE SPENSER", "EMPIRE FLETCHER",
"EMPIRE BOMBARDIER" & "EMPIRE BENEFIT". 22884

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed LOCAL "Carrying Petroleum in bulk".

1 Dk, 2nd Dk clear of cargo tanks. "Longitudinal framing at bottom and at deck".

Cell DB u E 70' 156t, DTf 25' 275t, FPT 150t, APT 88t.

FK, 17 BH, Lloyd's A & CP

P 93' B 46' F 51'

Mohy Aft

O.L. 483.0'

E.S.D.

ct

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L.: (A bower anchor and 60 fathoms of chain cable to be supplied).

Noted



© 2021

1.c.8

1.10.43

Lloyd's Register Foundation

002602-002610-0266