

No. of Aux./Donkey Boilers W.P.  
Surveyed Afloat or in Dry Dock Drydock  
Nature of Survey Part Mch. & BS  
Was Damage Report issued? no Int. Cert.? yes

Hull  
+100 A1 Shelter Dk. with  
fbd. 12/54  
+LMC 3/52  
BS 4/54

4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME ESPAÑA

REPORT N.Y.

No. 57166

### Reclassification

Machinery survey partly held 10.56.

Only item which can be credited towards  
reclassification is starboard screwshaft

It is submitted that the  
vessel WILL BE eligible for reclassification  
with ~~be~~ the record of ISCL (S) 10.56  
when the survey has been  
completed. as above.





© 2020

Lloyd's Register  
Foundation

002611-002619-0017

THIS IS SUBMITTED FOR THE INFORMATION OF THE COMMITTEE.