

Received from Chief Ship Surveyor

27 APR 1961

SHIPS NAME

"ELLAROO"

REPORT NO.

No. 8902

EA

Outstanding Conditions of Class:

SUBJECT to shell plate D.10
(s.s)(holed and doubled) being permanently repaired by
the Special Survey, and to the steel main mast being
repaired at the earliest opportunity.

ACTION is DEFERRED for Special Survey by 2,61.

S.R.L. Appendix. (~~As before or None~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat prior to the ship
proceeding to NAMAQ for breaking up.

Recommendation:

SUBMITTED ACTION be DEFERRED pending
further information.

24.4.61.



© 2020

Lloyd's Register
Foundation