

1

ACTION is DEFERRED FOR EXAMINATION
IN DRYDOCK AFTER GROUNDING

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME..... "FLORENCE COOKE"..... REPORT..... Gl.s. No. 87354.
JD.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey..... Docking. Damage repairs. When due
S.R.L.

N O T E D

SUBJECT to set up shellplates A.8 & 9, B.10 (s.s.), A.8,9 & 10, B.8 & 9 (p.s.) also buckled bilge keel (s.s.) being dealt with by the Special Survey.

DELETE FROM S.R.L.
Drydocking (grounding).

BM.
29.9.51.



© 2020

Lloyd's Register
Foundation

002630-002638-0212