

LLOYD'S REGISTER OF SHIPPING

Fondé en 1760 — Réorganisé en 1834

Reconnu par la Loi sur la Sécurité de la Navigation Maritime
(Arrêté Ministériel du 5 Septembre 1908)

Télégrammes : LLOYDREG

Téléphone 42.15

202, Quai George-V
LE HAVRE

RECEIVED

23 SEP 1948

ANSD. *rkq.*

LE HAVRE, 20th September 1948

"H"

Dear Sir,

ESSO NORMANDIE

In reply to your enquiry of 16th inst. I would explain that no report nor further mention of this case was made, as no actual Survey was undertaken.

The Owners requested a local Firm to prepare a steel re-shaft for a turbo feed pump for this Vessel and I called at the works and examined the billet which was subsequently rough-turned. Then the Owners obtained spares and the whole thing was dropped and the order for the spare shaft cancelled.

The Owners state that the Vessel will be placed in drydock here about the beginning of October when the port turbo Generator will be opened up for examination of the gears and pinions.

Yours faithfully.

Leslie S. Sims
Leslie S. SIMS.

Surveyor to Lloyd's Register.

The Secretary
LONDON.-



Lloyd's Register
Foundation

002639-002646-0069

E.

Referred to Mr. Perris.

[Handwritten signature]

[Handwritten scribble]

[Handwritten scribble]

[Handwritten signature]

1881

1881

RECEIVED



© 2020

Lloyd's Register
Foundation