

[Thin Copy for attaching to Report.]

# YD'S REGISTER OF SHIPPING

REGISTERED WITH THE BRITISH CORPORATION REGISTER

Port KOBE

13th January, 1961.


Kobe Rpt. 9

No. 8595

Sirs,

With reference to the  
now being held on the Steamer  
IR<sup>N</sup> 5450 tons gross of Hong Kong  
to inform you that, in consequence of  
condition of this vessel's No. 1 generator steam  
piston valve also windlass engine shaft  
and wheel  
it will be my duty to recommend to the  
Committee that the same be rebored at the  
the end of Special Survey now ~~is~~ due  
provided for in the Rules, an extract from  
appears on the other side:—the con-  
dition of the vessel's character in the  
Register Book to be subject to the  
fulfilment of this condition.

Yours faithfully,

  
Engineer Surveyor to Lloyd's Register.

P. Mason

Hong Kong Fir Shipping Co., Ltd.,

Hong Kong.

002647-007652-0064

SHIPPING


(Thin Copy for attaching to Report.)

# LLOYD'S REGISTER OF SHIPPING

WITH THE BRITISH CORPORATION REGISTER

Port Kobe

13th January, 1961.



## LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

### Extract from the Rules of the Society respecting Engines and Boilers:—

In the event of either the engines or boilers appearing impaired to such an extent as to render it desirable that both be submitted to an additional survey within the period prescribed above, a certificate for either engines or boilers for a limited period will be granted according to the nature of the defect.



© 2021

Lloyd's Register  
Foundation

Good

length

mean diam.