

COPY

Kobe Rpt. 8 No. 8595

LLOYD'S REGISTER OF SHIPPING



B-68113

Port KOBE

Date 13th January, 1961.

This is to Certify that I have

veyed the s.s. "CHINA FIR" 5450 tons gross of Hong Kong whilst
 at and in dry dock at Osaka on the 23rd December, 1960 and subsequently
 account of General Examination for Postponement of Special Survey 'C'
 12,60 and Damages stated to have been caused by 1) grounding at Belawan
 7th July, 1960, 2) heavy weather Mormugao/Osaka between the 7th and
 December, 1960

that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report, stating that all repairs recommended by
 have been completed to my satisfaction, also that I will
 commend that she be continued as classed with fresh record of dry-
 ing 12,60, subject to shell plate K5 (s.s.) also defective frame rivets
 frames 78 and 79 in way of aux. condenser (port) be specially examined
 dealt with as necessary next Special Survey.

R. Brown

R. Brown Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

| | | | |
|-----|--|--------|-----------------------------------|
| AS | Annual Survey | SS | Hull Special Survey |
| BiS | Biennial Survey | SS(Dr) | Hull Special Survey (Drilling) |
| DS | Docking Survey | SS(M) | Hull Special Survey (Modified) |
| NS | Cargo Battens not fitted (No Sparring) | SS(P) | Hull Special Survey (Progressive) |

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
 the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
 be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
 Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
 or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

KOB

RB:ht

FOR LONDON

1900-159200-1h9200