

Received from Chief Ship Surveyor 8-JUN 1959

SHIP'S NAME "CROSTAFELS"

REPORT Rot. No. 47302

VC

Outstanding Conditions of Class: SUBJECT to shall plate G.2 (s.s.f.) and (holed) No.2 tank top plating (s.s.) being specially examined and dealt with as necessary by next Special Survey, and to permanent repairs being affected to Nos. 3 & 5 D.B. tank top plating by the Special Survey.

Indorsement of Class (B) (~~As before~~ or None)

Surveys due: SPECIAL SURVEY (C) due 3.59. postponement until 12.59 approved 26.5.59 G.E. held Bmn. 4.59.

ature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to sheerstrake plating and first below and deck plating etc. in way of midship deckhouse (s.s.f.) on account of collision damage.

pecial Features:

s Interim Certificate in order (Yes ~~No~~ ~~None~~)

tems Outstanding: (If any for S.S. or A.S.)

All items.

S. to be completed by:

commendation: SUBJECT as above, and to indented sheerstrake plating and first below and deck plating etc. in way of midship deck house (s.s.f) being permanently repaired by the S.S. but ACTION be DEFERRED for Special Survey.

As now. SUBJECT.

JS
5/6/59