

Cristina Maza 9

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Steel S.S. "LALANDE". Report GlS. No40372

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24 E 02.)

of Survey

When due

The downton pump has been dispensed with for the present.

100 A.1. Shelter Dk. with freeboard.

2 Dks. (Steel) and Shelter Dk. (Steel).

Cell DB 395' 1289t. MT 22', 469t. DTa 27' 1015t.

FPT 118th. APT 20t.

FK. 7 BH. to Shelter Dk. | BH to Upper DK. pt. Cem.

Lloyd's A. & C.P. F on Shelter Dk 46'

[Handwritten signature]

24. 9. 20.

It is concluded a webframe ^{is} fitted in the forward deep tank or oil bunker, as shewn ^{on} approved plan, but the Surveyors should state if this is so.

Lpls: 19. 10. 20

[Handwritten signature]



© 2020

Lloyd's Register Foundation

002653-002658-0118