

Received from Chief Ship Surveyor

20 JAN 1961

IE "FORMA"

REPORT

KRH

No. 3215

EA

g Conditions of Class:

NONE

endix. (As ~~before~~ or None)

Present Survey: (Afloat and in dry dock)

Docking:- Temporary repairs to wasted keel plate.

tion:

SUBMITTED record of DS 11,60 be assigned, subject to wasted keel plate No.2 being specially examined and dealt with as necessary next drydocking.

11,60

Subject.

R. J. Tol
13/1/61



© 2020

Lloyd's Register
Foundation

002659-002666-0023

GENERAL

State
"to r.
1,55,

class