

The screw shaft being drawn and examined  
on completion of present voyage.

4E

subject to

25 JAN 71

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME.....

CAMILLA


REPORT.....

Hul

No. 65563

MBS due 10.59 now held.

TS due 10.61 now held.



S.R.L. The Surveyor reports screw shaft replaced  
by previously used spare and recommends  
the item be deleted.

IT IS SUBMITTED this vessel is eligible to remain  
as classed with fresh record of MBS 1.60 and TS 1.60 without  
special condition.

*Handwritten signature*

22.1.60.

002659-002666-0055

© 2020

Lloyd's Register  
Foundation