

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Kelt

Rpt.

Mad

No.

15919

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Vapour Expansion

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of

approved type


no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ Rule 237**Dynamometer test to be forwarded**Yes**Yes**1.3.37*

It is concluded no fuses are fitted on the live ends of the switches but this should be confirmed—

*no fuses on live ends
per J. 12/4/37*



© 2020

Lloyd's Register
Foundation

002659-002666-0062