

*For correspondence chain
photos of defective cable, see bag attached
at back of this report.*
COPY.

J. E. R. J.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

20th March, 1936.

Dear Sirs,

M.

I am in receipt of Mr. Edwards' letter of the 19th instant regarding alterations carried out to the hatch webs and bearing pieces of the S.S. "FULHAM". The Burntisland Shipbuilding Co's Yard No. 193, and I have to state that the contents have been duly noted.

As desired the sketch of hatch web snugs for this vessel has been added to the plans forwarded with your Report No. 19016, and the plan of hatch web bearers approved for the sister vessels Nos. 194/5, and forwarded for reference, is returned herewith.

Thanking Mr. Edwards for his attention in

I am, Dear Sirs,

Yours faithfully

(P.C. G)

The Surveyors,

LEITH.

002659-602666-0080



© 2020

Lloyd's Register
Foundation