

Ship's name ADNA Survey port HKG No. 15972


Class is subject to repairs to the M.E driven L.O. pump casing being examined by 2/61 (Metalock) repairs to the M.E. cylinder cover No. 4 being re-examined by 2/61 (Metalock). Last survey date 17/12/60

9-FEB 1961

Nature of present survey
DS - CS advanced.
ABS due 2/61 now held.

Nature of repairs
SRL Both items re-examined and found satisfactory, Surveyor recommended both items be deleted from SRL and entered in the 'Appendix'.


Recommendation IT IS SUBMITTED that this vessel is eligible for the record ABS 12/60 without special conditions.



8.2.61.

S.R.L. offender dock
class engine driven L.O. pump replaced by Metalock
class engine dock cylinder cover replaced by Metalock

To complete surveys partly held



Lloyd's Register
Foundation