

30 MAR 1960

Received from Chief Ship Surveyor

SHIP'S NAME "CAPTAIN JOHN" REPORT Rot. No. 49031

standing Conditions of Class: SUBJECT to shell plates A.3, C.2 and D.2 (s.s.) being specially examined and dealt with as necessary at the Special Survey.

R.L. Appendix. (As before ~~or None~~)

ature of Present Survey: (Afloat and in dry dock)

Docking: Permanent and temporary repairs to H.W.damage.

commendation:

SUBMITTED record of 'DS 3,60' be assigned, subject as above, and to fractured shell plates E.5 and H.5 (p.s.), E.6 and J.5 (s.s.) being dealt with by the Special Survey.

DS 3,60 Subject

IN S.R.L. APPENDIX.


Indents in keel plate No.2 and a few shell plates (p & s).

A.16 (s.s.) set up.

B.13 (s.s.) doubled.

OFFICE NOTE:

Postponement of S.S. if required cannot be granted - see Rot.letter dated 11.3.60.



© 2020

Lloyd's Register
Foundation

29/3/60