

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

17th July, 1931.

Dear Sirs,

E. With reference to Newcastle Report No. 87354 on the machinery of the s.s. "PAN BOLIVAR" I have to say it is concluded that the boiler safety valve area is in accordance with the Rules and that the screw stays are nutted on the end plates as approved, but I shall be glad if you will state whether this is so and also state the diameter of the safety valves.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

NEWCASTLE.



© 2020

Lloyd's Register
Foundation

002667-002673-0170