

Received from Chief Ship Surveyor

SHIP'S NAME "CORILLA" REPORT Sng. No. 13725

Outstanding Conditions of Class: NONE.

R.L. Appendix. (As before ~~or None~~)

Structure of Present Survey: (~~Afloat~~ and in dry dock)

Docking: Permanent/deferred wear and tear repairs.


Recommendation: SUBMITTED record of 'DS 12,59' be assigned, subject to rudder axle post (corroded) being re-examined and dealt with as necessary by 12,60.

DS 12,59 Subject

IN S.R.L. APPENDIX.
(Bottom hogged overall 2 $\frac{3}{4}$ ")

NOTE:-A pre Special Survey examination in accordance with Circular No.2106 carried out at Singapore (See Sng.Rpt.No.13149 dated 3,59 with attached drillings). See also Ship Research Dept. Memo dated 6.8.59.

C.S.S. Records Dept.
to note.



© 2020
Lloyd's Register
Foundation
Attal
9/2/60