


# LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

14th January, 1960.

**This is to Certify** *that I have*

*Part*  
 Surveyed the/Machinery of the m.v. "CORILLA" 8100 tons gross of  
THE HAGUE, whilst the vessel was in drydock and lay afloat  
 at the Port of Singapore on the 28th December, 1959 and subsequently  
 on account of Auxiliary Boiler Survey,

*and that I will transmit to the Committee of Lloyd's Register of*  
*Shipping, London, a Report stating that all recommendations made by*  
*me in connection therewith have been carried out to my satisfaction; also*  
*that I will Recommend that in the case of this Vessel the following*  
*Survey Records be made in the Supplement to the Register Book*

ABS 1/60 now

*and that her Machinery Classification Record be continued in the Book.*

**Parts now examined:**

(C.S. Items only)

Auxiliary boiler examined throughout, together with it's  
 safety valves, mountings, manhole doors and fastenings and all  
 found, or now placed, in good order. Subsequently, boiler examined  
 under steam and safety valves adjusted to required pressure; oil  
 burning arrangements and remote controls examined under working  
 conditions and found satisfactory.

Compression Ring Thicknesses Forward  $17/32$ " Aft  $19/32$ "


*W. Ward*  
 Engineer Surveyor to Lloyd's Register  
 (W. WARD).

**KEY TO ABBREVIATIONS**

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



007674-00681-0048