

Received from Chief Ship Surveyor

113 MAY 1959

SHIP'S NAME "FORT STEVENS"

REPORT Cff.

No. 60837.

Standing Conditions of Class:

Subject to sternframe solepiece  
(E.W. & reinforced 12,56 & previously) being specially examined  
next drydocking.

Assessment of Certificate (~~As before~~ or None)

Where of Present Survey: ~~(Afloat and in dry dock)~~

Docking; W & T repairs; Equipment - 5 lengths of chain cable  
worn below renewal size: replaced & verified.

Recommendation:

SUBMITTED record of 'DS 4,59' be assigned as recommended  
SUBJECT to sternframe solepiece (E.W. 4,59 and E.W. & reinforced  
12,56 & previously) being specially examined next drydocking.

DS 4,59. Subject, amended.

OFFICE NOTE.

Structure reinforced Fal. 10,52.  
Docking brackets fitted - Fal. 1,54,  
with minor set up in keelplates left  
unfaired.



© 2020

Lloyd's Register  
Foundation

Handwritten signature and date: 11-5-59