

12 NOV 1950

SHIP'S NAME "DILOMA" REPORT Skm. No. 12812

GB

Outstanding Conditions of Class:

SUBJECT to indented side shell plating (p & s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (~~As before~~ or ~~None~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs on account of grounding damage.

Recommendation:

SUBJECT as above, but further ACTION be DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.
Drydocking(grounding).



W.S.T.

© 11-50

Lloyd's Register
Foundation