

COPY.

# Lloyd's Register of Shipping.



Port Oslø

23rd August 1933

**This is to Certify** that

Per Björn-Röli and P. Rido

the undersigned Surveyor to this Society did at the request of  
A/S Drammens Jernstøberi & mek. Verksted, on the 18th May, 21st June,  
7th July and 4th August, 1933, examine the compressors, with  
cylinders, pistons, rods, shafting, bearings, crossheads, bedplates,  
condenser casings, headers and coils, evaporator casings, separators  
etc. for the refrigerating machinery intended to be fitted on board  
the yard no. 476, being built by A/B Götaverken, Gothenburg.  
The separator parts were carefully examined during construction,  
and were tested and marked as follows:-

Condenser casings:- Hydraulic pressure 2 Atm.

Marks:- R Lloyd's test 2 Atm. 7.7.33. P.B.R.

Condenser coils and headers:-

Hydraulic pressure 210 Atm., air pressure 105 Atm.

Marks:- R Lloyd's test 210 Atm. 7.7.33. P.B.R.

Compressor cylinders:- Hydraulic pressure 210 Atm. air pressure 105 Atm.

Marks:- R Lloyd's test 210 Atm. 21.6.33. P.B.

Oil separators:- Hydraulic pressure 210 Atm. Air pressure 105 Atm.

Marks:- R Lloyd's test 210 Atm. 4.8.33. P.B.T.

CO<sub>2</sub> dryers:- Hydraulic pressure 210 Atm. air pressure 105 Atm.

Marks:- R Lloyd's test 210 Atm. 21.6.33. P.B.

The parts were found perfectly sound and tight at the above  
pressures and the workmanship throughout is good.

Fee incl. travl. expenses.

Kr. 195.-

Kunde Per Björn-Röli  
Surveyors

Lloyd's Register of Shipping

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly ex-  
ecuted, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held res-  
ponsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register B-  
published by the Society, or for any error of judgment, default, or negligence of the Committee or any Membe-  
r, or of the Surveyors, or other Officers or Agents of the Society."