



CANADA

DEPARTMENT OF TRANSPORT

YOUR FILE NO.....

OUR FILE NO. 9562-466

606/325 Granville Street,  
Vancouver 2, B.C.,  
August 15, 1960.

Mr. T. Taylor,  
Lloyd's Register of Shipping,  
355 Burrard Street,  
VANCOUVER 1, B.C.

Dear Sir: M.S. "FORT HEARNE"

Further to report of inspection carried out on  
this vessel on June 5, 1960, at Tuktoyaktuk, N.W.T.

*afloat ← see Canada  
Dept letter of  
27-6-60,*

Examination was made of hull planking externally,  
sheathing, bow protection plates, stem, stern post, as far as  
could be seen afloat.

Hull was examined internally. interior of hold,  
machinery space, fore and aft peak spaces, bulkheads, decks,  
bulwarks, hatches, hatch coamings, beams, beam knees and ceiling  
timbers.

All closing appliances examined, ventilators, air  
pipes, machinery casing, companionways, scuppers, side scuttles,  
freeing ports, doors and coamings to crew's quarters, engine room.

Hatch covers, tarpaulins, wedges, battens.

Machinery - Examined pumps and piping, air tanks  
examined externally, safety valves tested. Fuel tanks examined  
externally. Main engines and auxiliaries seen in operation.

All items left in good order.

Yours very truly,

RECEIVED  
AUG 16 1960  
JM/IS  
ANSWERED



© 2020  
*J. Moorcroft*  
J. Moorcroft,  
STEAMSHIP INSPECTOR.

Lloyd's Register  
Foundation