

6

s

21st November, 1952.

Six

s are

KOBE

945. As recommended. *A*

I MARU". 905. As recommended. It is concluded that the subject regarding permanent repairs to indented shell plating, etc. in way of No. 1 upper and lower 'tween decks (port side) has been dealt with at this time.

It is also concluded that your recommendation that permanent repairs should be effected to indented shell plating (port side forward) by the next Special Survey, should have read, "by completion of the Special Survey", but I shall be glad if you will confirm these matters.

934 "WARORA". As recommended, except that a notation of SINC CS 9,52

Cont./.....
Lloyd's Register
Foundation

002711-02716-0091