

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Stl Se " EBRO "* Rpt. *Rot* No. *20163~*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

*1st Long*Transverse No. *1479*Depth "d" *11' 7 1/2"*Framing: Table No. *✓*Description *angle frames as approved.**2nd* Longitudinal No. *4263*Proportions $\frac{\text{Length}}{\text{Depth}} =$ *9.1*

Deck Sheerstrake

*as approved**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel) for Towing Services

1 D¹ Leak

Tanks in way of tunnel 14' 8 1/2", D.T.f 9' 2 1/2", F.P.T. 9 1/2", A.P.T. 2 1/2".
 B.K 6 1/2", 4 B.H, Cen, Lloyds A.C.P.
 B 39', F 12'.



© 2020

Lloyd's Register
Foundation

002725-002735-0059

© 2020
Lloyd's Register
Foundation