

Surveyed Afloat or in Dry Dock **Both**  
Nature of Survey **Part C.S., D.B.S., T.S.**  
Was Damage Report issued? **No** Int. Cert.? **Yes**

Carrying Petroleum in Bulk.  
S.S. Bhn (Dr) 3.55  
Dkg. 6.57.

Eng. C.S. 3.55.  
B.S. d 7.57.  
T.S. C.L. 1.55

57.

4E

22 JUL 1958

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME ESSO HULL REPORT hwc No. 115369

C S advanced

DBS due 7/58 now partly held

Screwshaft examined


Screwshaft liner found worn and scored. Screwshaft renewed and a new liner fitted to old shaft - now spare. Propeller renewed.

It is submitted that this vessel is eligible for THE RECORD.

S (N) 6/58 now  
and DBS 6/58 when the safety valves of the exhaust gas boiler are adjusted

R

22/7/58



© 2021

Lloyd's Register  
Foundation

002736-00743-0221