

Received from Chief Ship Surveyor

19 JAN 1956

SHIP NAME

"SYDNEY FREEZE"

REPORT

Kob.

No. 3161

Standing Conditions of Class:

(p & s) being renewed by 8,55.

Subject to windlass chain cable lifters

ACTION is DEFERRED for Equipment (a bower anchor and 60 fathoms of chain cable to be supplied at the earliest opportunity).

Endorsement of Class (B) (~~As before~~ or None)

Signature of Present Survey: (~~At sea~~ and in dry dock)

SPECIAL SURVEY (C) due 3,56: Conversion to O.F.:

A bower anchor and 60 fms. of c.c., as above, placed on board & verified. Condition of class dealt with: Deferred repairs.

Recommendation:

SUBMITTED record of docking 9,55 and Notations of "ss.Kob. 9,55" also "O.F. 9,55" be assigned as recommended, without special condition but with Endorsement (B).

9,55 Kob.)
ss.Kob. 9,55.) Without.

INSERT IN .B.

x "O.F. 9,55"

ENDORSEMENT OF CLASS (B).

Shell plate No.4 (p.s.f.) indented.




© 2020

Lloyd's Register
Foundation

IT IS FURTHER SUBMITTED the Surveyors be
 advised it is concluded the D.B. tanks converted to oil fuel
 can also carry water ballast, but if this is not the case,
 they should furnish the amended capacities for D.B. tanks,
~~if so many tanks W.B., remainder O.F. or F.W.~~

2411

OBM.
 18.1.56.



© 2020

Lloyd's Register
 Foundation

CLASSIFICATION