

Received from Chief Ship Surveyor

11 MAR 1960

SHIP'S NAME

"CERONIA"

REPORT s (a) H.Kg.  
(b) Sng.

No. 15257  
No. 13759

Standing Conditions of Class:

SUBJECT to fractured shell plate (s.s.)  
in way of E.R.deep frame being permanently repaired next  
drydocking.

R.L. Appendix. (~~As before~~ None)

Structure of Present Survey: (Afloat and in dry dock)

- (a) Docking: ~~Swag~~ and tear and subject item repairs:  
Drilling of shell and deck plating for assessment of  
Special Survey requirements.
- (b) Supply and verification of equipment.

Recommendation:

SUBMITTED record of 'DS 12,59' be assigned  
as recommended, but without special condition.

DS 12,59 Without.

IT IS SUBMITTED H.Kg. Rpt.No.15257 be sent to the  
Ship Research Department for consideration of shell and deck  
thicknesses in order that the Owners may be advised of the extent  
of anticipated repairs for the Special Survey.