

The class is subject to the inboard steam dynamo crankshaft
being renewed. 4.58

28 JAN 1959 4E

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

AME ALBA REPORT Pal. No. 185

Docking.

C.S. Advanced.

DBS due 5.58 now held.

The main engine crankshaft found cracked and both forward
and after crankshaft sections now renewed, bedplate examined
together with holding down bolts and chocks and found
satisfactory, after fitting new crankshafts the alignment
checked found satisfactory also a sea trial carried out.

S.R.L. ^a The new crankshaft now fitted to the inboard
steam dynamo engine, to be deleted.

IT IS SUBMITTED that this vessel is eligible
for the record DBS 12.58 without special condition.



2020
27.1.59.



Lloyd's Register
Foundation

9700-001771-0076