

002754-002761-0175

5m,7,32.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M.S. "FAGERFJELL"

Rpt.

Mmo

No. F.E.1366

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Signature of Surveyor

In a letter dated the 8th instant the Malmo Surveyor writes that this vessel, after completion, sustained damage through grounding whilst on trial.

The vessel has been placed in dry dock and a specification for repairs drawn up and it is stated these will be carried out by the Builders under survey.

It is submitted no action is necessary pending the receipt of a further report from the Malmo Surveyor.

The Malmo Surveyor should be requested to forward the approved Rudder plan, for reference in dealing with the First Entry report, by return
12.15/6/35.

Plan recd. Sec. & rudder checked plan returned

12.15.35
Lloyd's Register
Foundation