

Please return to Mr. Spring

Received from Chief Surveyors

NAME Steel S.S. "ARANA"

Report 9/12

No. 39493

For the CHIEF SHIP SURVEYOR

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

When due

The Downton Pump has been dispensed with for the present, but it is  
cluded the Owners are agreeable to fit same when requested.

100 A.1. (steel)

2 Dks (steel)

Cell DB 260' 661t.

FPT 69t.

APT 180t.

FK. 68H. 1st com.

Lloyd's A.C.P.

P33, B 81, F 52



all.

1-1-20

It is concluded, the Tank top plating is increased in thickness as  
in way of rollers & that the breadths of keel straps are as required  
the Surveyors should be requested to state if this is so

002762-002769-0060

© 2021

Lloyd's Register  
Foundation