


"SALLY MAERSK"

It is submitted that action be deferred pending the receipt of the Gothenburg Surveyors' report on the examination in dry dock proposed by the Owners to entitle the vessel to a "Commissioned" notation.

It is further submitted the Copenhagen Surveyors be requested to state whether the steel used in the construction was tested by former Surveyors to this Society.

They should be informed it is concluded the applicable requirements of Section 20 of the Rules have been complied with and that the number of shifting beams fitted in the hatchways is as given in the freeboard report, but they should state if this is so.

As the length of the forecastle on the plan of profile "as built" and in accordance with Circular 1551 appears to be 40.7', they should be requested to state whether they are correct in reporting a length of 39.28'.



14.11.45

© 2021

Lloyd's Register
Foundation

002762-002769-0113

J. P. Bydersee.

2 off

1000

7/7

L 100 10

2180

1950

1370

200 7

230 9

230 9

165

760