

Received from Chief Ship Surveyor

SHIPS NAME "INDIAN NAVIGATOR"

REPORT

HAM

No. 10093

EA

Outstanding Conditions of Class: SUBJECT to bottom shell plating being specially examined at each drydocking.

S.R.L. Appendix. (As before ~~or none~~)


Nature of Present Survey: (Afloat and in dry dock)

Docking: Examination of S.R.L. Appendix items.

Recommendation:SUBMITTED record of DS 11,60 be assigned, subject as above.

DS 11,60

Subject.

S.R.L. APPENDIX (AMENDED)Minor bottom plating (stiffened - Ham 1,53).
Minor corrugations unfaired).OFFICE NOTEBottom shell plating stiffened in accordance with Circ.No.1888
Ham.2,51. Modified and additional stiffening fitted - Ham.3,55
(with minor corrugations unfaired).Lloyd's Register
Foundation