

WALLEM & CO., LTD.

AGENTS FOR

WALLEM & COMPANY A/S
BERGEN

WALLEM & CO. (SINGAPORE) LTD.,
SINGAPORE.

WIKOO DOCKYARD & ENGINEERING CO.
OF HONGKONG LTD.

NORSE STEAMSHIP COMPANY S.A.,
PANAMA.

AVIATION AGENCY

ENS SOUTH AMERICAN AND FAR EAST
AIR TRANSPORT (S.A.F.E.)

SHIPOWNERS

BROKERS—SHIPPING AGENTS
BUNKERING AGENTS



ASSOCIATE

WALLEM LAMBERT BROTHERS LIMITED,
HONGKONG.

P. O. BOX 40,

TELEPHONE: 38041/5

TELEGRAMS: "WALLEM"

TELEX NO. HKG 17

HONGKONG & SHANGHAI BANK BUILDING.

HONG KONG.

27th January, 1960.

Lloyd's Register of Shipping,
LONDON

Dear Sirs,

S.S. "INDONOR"

We refer to your letter of the 22nd instant, regarding some outstanding recommendations, and would like to comment as follows:

- 1) The gypsy shafts of the windlass have been ordered to the Droogdok Maatschappij, Tandjong Priok, Djakarta, which shall be installed as soon as the vessel arrives there during February;
- 2) The tunnel top plating in No.3 hold shall be inspected and repaired at Djakarta during February after complete discharge of inward cargo;
- 3) The bower anchor has been purchased and tested at Hongkong and has been shipped down to Djakarta by the s.s. "Eastern Mariner", ETA Djakarta 1st February, same shall be put on board the "Indonor" upon her arrival there; and
- 4) The propeller shall be examined by the Lloyd's surveyor at Djakarta and repaired or renewed at her next drydocking.

Hoping that this will meet with your enquiry.

Yours faithfully,

DR. WALLEM & CO., LTD.

I. Heide-Holtan
MARINE SUPERINTENDENT

I. HEIDE-HOLTAN.

IHH:KKL

c.c. Lloyd's Register of Shipping, HONGKONG.



© 2020

Lloyd's Register
Foundation

MOITACITUBAJO

002770-002783-0352

(Cert. B)