

COPY

# LLOYD'S REGISTER OF SHIPPING

5692



Port DJAKARTA

Date 17th December 1959

**This is to Certify** *that I have*

*Surveyed the S.S. "INDONOR" 2828 tons gross of Panama, on the 9th December 1959 and subsequently whilst afloat at Tandjong Priok on account of windlass repairs,*

*and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will Recommend that she be retained as classed, subject to both windlass gypsy shafts being renewed by the end of February 1960, tunnel top plating in No.3 hold being examined and dealt with as necessary at the next Special Survey, and to bower anchor (supplied 12,58) being placed in accordance with Rule Requirements at the earliest opportunity.*

*J.A. Boater*

Surveyor to Lloyd's Register.

J.A. Boater

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 100m,4,59

(MADE AND PRINTED IN ENGLAND.)

002770-002783-0355