

bs

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME

"DESMOULEA".

Report _____

Grk. _____

No. _____

20881.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

re of Survey

FIRST ENTRY

~~When due~~

This is a sister vessel to the "DAVILA", "DOSINIA" and "DELPHINULA".

LOCAL "Carrying Petroleum in bulk"

1 Dk, 2nd dk clear of cargo tanks, "Longitudinal framing at bottom and at deck"

Cell DBuE 69' 162t, DTf25' 281t, FPT143t, APT94t

FK, 17BH, Lloyd's A & CP.


P93' B45' F51'

Mchy. aft.

O.L. 483'

E.S.D.

ct



1.c. 10

18.1.40.

See letter 29.1.40

It is concluded ~~the~~ windlass and steering arrangements have been tried under working conditions and found satisfactory, but the Surveyors should state if this is so.



© 2020

Lloyd's Register Foundation

002784-002789-0079