

LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE

8th December, 1959.

This is to Certify that I have

Part

Surveyed the Machinery of the m.v. "DESMOULEA" 8120 tons gross of LONDON whilst the vessel lay afloat and was in drydock at the Port of Singapore on the 12th November, 1959 and subsequently on account of Dooking, TSCL, ABS and CS of Engines,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book TSCL 11/59 and ABS 12/59 now and OS (with date) when the survey has been completed,

and that her Machinery Classification Record be continued in the Book.

Parts now examined:
(C.S. Items only)

Propeller. Aft end of stern bush. Underwater fastenings. Screw shaft. Auxiliary Boiler.

Main Engine

Nos. 3 and 5 cylinders, covers, pistons and rods, valves and gears.
Nos. 1, 3, 5 and 8 connecting rods, top ends and guides, crankpins and bearings.
Nos. 1, 3, 5 and 8 journals and bearings.
Thrust block shaft and bearings.
Intermediate shaft and bearings.

over.

Engineer Surveyor to Lloyd's Register
(W. WARD).

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error or judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

