

The class is subject to the main engine bedplate and all astern guides and the thrust block being re-examined and dealt with as necessary at the next Special Survey, and to the centre boiler not being used until back end plate repaired and new feed check valve chest fitted.

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME "CAYMONT" REPORT Cbo. No. 4156.

MBS due 2.58, partly held 2.58, now advanced.

SRL : The backend plate of the centre boiler now repaired and a new main feed check valve chest fitted. To be deleted.

IT IS SUBMITTED that this vessel is eligible for THE RECORD, MBS 2.58, on completion of the Survey, subject to the main engine bedplate and to the astern guides and thrust block being re-examined and dealt with as necessary at the next Special Survey, without other condition.

To complete the MBS : The port and starboard boilers to be examined, safety valves of all boilers adjusted, and the oil burning arrangements examined under working conditions.

9.4.58.



© 2020

Lloyd's Register
Foundation

002784-002789-0156