


COPY

LLOYD'S REGISTER OF SHIPPING



Port LONDON.

31st August, 1961.

This is to Certify *that I have*

Surveyed the Machinery of the M.V. "HIPPINHAM ORANGE", 10364
tons gross of London for advancement of C.S. and repairs
to port main engines

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
... (with date) when the survey has been completed.

and that her Machinery Classification Record be continued in the Book.

subject to the starboard main engines not being used until repaired
and to any other outstanding conditions of class being dealt with
as previously recommended, being fit in my opinion to proceed to
Long Kong via ports of call on the port main engine only, tugs to
Parts now examined: be available leaving and entering ports.

(C.S. Items only)

PORT MAIN ENGINES:

No: 10 crankshaft journal and bearing.
Engines tested working and manoeuvring.

E. Green.

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.


SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

B.L. GREEN.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, the Surveyors, or other Officers or Agents of the Society."

Pl. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)



© 2020

Lloyd's Register
Foundation

002790-002797-0049