

2500, 12, 19.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel SS. "FINVOY"

Report Gls.

No. 40,134

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINE SURVEYOR~~

(In cases which have to be submitted to the Classing Committee, the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

✱ 100 A.1. (Steel)

1 Dk. (steel)

"Well Dk"

FPT 54t.

APT 9t.

BK 7". 3BH. Cem. Lloyds A.Y.C.P.

Q 49', B 9', F 26'

Machy aft.

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.

002790-002797-0104

state i

Spacin

CENTRE GIRD