

propeller boss YES.

If the liner is in more than one length are the junctions made by fusion through the whole thickness

the liner does not fit tightly at the joint between the bearings in the stern tube is the space charned with a plastic material insoluble in water

"Western Sun."

Phl. 6112.

It is submitted the surveyor  
be asked to state the relative  
positions of the two boilers with a view  
to distinguishing their pressures in the  
Register Book.



© 2020

26/6/30

Lloyd's Register  
Foundation

002798-002807-0023

Are all **Sea Connections** fitted direct on the skin of the ship YES.

Are they fitted with Valves or Cocks

Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates YES.

Are the Overboard Discharges above or