

1 OCT

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME

"JULIAN PRESA"

REPORT

Cff.

No.

60247

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

This ship is over 26 years old.

The class is subject to Nos. 1, 2 & 3 D.B.tanks being examined internally in dry dock by 8,57 (wastage) and dealt with as considered necessary, also to shell plates E.3 & 4; F.4 & D.3 (p.s. from fwd) being dealt with by next Special Survey, with Endorsement of Certificate.

The CARDIFF Surveyors report (9,57), this ship examined in dry dock and Nos. 1, 2 & 3 D.B.tanks examined internally. Temporary repairs have been effected and permanent repairs recommended to all the bottom shell plating in way of the above tanks on ship's arrival at a North East Coast of England or West Coast of Europe repair port from present voyage, the structure being considered efficient for the proposed deferment.

In view of the above IT IS SUBMITTED NOTATION of 'DS 9,57' be assigned, subject to permanent repairs being carried out to the structure in way of Nos. 1, 2 & 3 D.B.tanks on completion of the present voyage to a North East Coast of England or West Coast of Europe repair port from present voyage, and to shell plates E.3 & 4, F.4 and D.3 (p.s. from forward) being dealt with by next Special Survey, with Endorsement of Certificate, but further ACTION be DEFERRED for Repairs.

SUBJECT
AMENDED.

ENDORSEMENT OF CERTIFICATE.

Indents in a few bottom shell plates.

S.P.R.
27.9.57.



© 2020

Lloyd's Register
Foundation

062802-602815-0170