

1

10th January, 1958.

one

NEWCASTLE/TYNE

114859, 4871, 4875, 4884, 4885, 4886, 4888,
4890, 4891, 4892 - As recommended.

I.C.NO.23" 114833 - As recommended.

114873 "CAMBERWELL" As recommended. It is concluded the boiler safety valves were adjusted to the required working pressure, but I shall be glad if you will confirm this point.

114880 "MURILLO" ex "TACOMA STAR" As recommended, except that notations of ES 5,57 and SPS 5,57 have been assigned.



© 2021

Lloyd's Register
Foundation

002816 - 002824 - 0041