

Received from Chief Ship Surveyor

14 MAY 1958  
9 JUN 1958

NAME "IKLA"

REPORT

Cpn.

No. 16901

Working Conditions of Class: Subject to indented shell plate A.1 (p.s.s.) set up, coffin plate and shell plate B.4 (p.s.f.) being dealt with at the next Special Survey.

Assessment of Certificate (~~As before~~ or None)

Place of Present Survey: (~~At float and~~ in dry dock)

Docking: Wear and tear repairs:

Damage repairs (grounding):

Examination of deferred items as above.

Recommendation:

SUBMITTED record of 'DS 2,58' be assigned, subject as above.

DS 2,58 Subject

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded they are in error in assigning a record of 'DS 2,58' when the last examination in dry dock is recommended as being 2,58 but confirmation is desired.

X2015



Lloyd's Register  
Foundation

93  
1-5-58