

4E

14 MAY 1958


Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... IKLA..... REPORT Abg No. 16901

Docking. Tailshaft seen.

Some damage to cast iron propeller sustained as a result of grounding and a spare propeller now fitted. Some repairs effected to the main engine and auxiliary machinery.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of TS (CL) 2.58.



© 2021

Lloyd's Register Foundation

002816-002824-0205