

Steamer "ILHA GRANDE".

Rio Report N°8110.

UPPER DECK DRILLINGS.

The following results were obtained by drilling of the Upper Deck. Systematic drillings were not possible due to a number of local doubling plates.

Where marked * the results were obtained by ultrasonic probe.

	<u>Strake.</u>	<u>Port</u>		<u>Star'd.</u>	
		<u>Fr.</u>	<u>thk.</u>	<u>Fr.</u>	<u>thk.</u>
75	Stringer plate.	52/53	.75" ✓	52/53	.80" ✓
	" "	97/98	.82" ✓	97/98	.80" ✓
	" "	117/118*	.75" ✓	-	-
	1st strake inboard	55/56	.60"	-	-
5/8	" " "	-	-	89/90*	.75"
	" " "	116/117	.60"	116/117	.56"
5/8	2nd " "	54/55	.70"	54/55*	.60"
	" " "	93/94*	.75"	-	-
	" " "	117/118	.50"	117/118	.56"
	3rd " "	87/88	.50"	87/88*	.50"
	" " "	128/129*	.30"	-	-
	Centre strake.	61/62	.32"	-	-
4	" "	86/87*	.30"	-	-



Lloyd's Register
Foundation

002816-002824-0277