

Class is subject to

24 APR 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME JAMAICA PRODUCER REPORT Lon No. 146999

Fracture in water box of the main condenser now repaired by Metalock process & waterbox recommended to be dealt with as necessary at next E.S. (due 5/67 & extended to 5/62)

It is submitted that this vessel is eligible to remain as **CLASSED**.

Only as now recommended

(Note:- this vessel is to be broken up.)

002838-002845-0160

© 2020
Lloyd's Register
Foundation