

COPY

LLOYD'S REGISTER OF SHIPPING



Port S I N G A P O R E .

6th February, 1960.

This is to Certify *that I have*

Surveyed the Machinery of the **s.s. "DIMITRIOS A. KYDONIEFS"** 4862 tons gross of ANDROS whilst the vessel lay afloat at the Port of Singapore on the 16th January, 1960, and subsequently on account of damage stated to have been caused by failure of Main Engine attached air pump bucket and chamber on the 21st December, 1959, whilst the vessel was at sea on voyage Colombo to Singapore, Repairs and Part MBS

and that I will transmit to the Committee of Lloyd's Register of

Shipping, London, a Report stating that all recommendations made by

me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book

MBS 2/60 when the survey has been completed

and that her Machinery Classification Record be continued in the Book.

subject to Main Engine, attached air pump being re-examined by end of March, 1960 (2 mos limit) and subject to any other conditions at present attached to the vessel's class being dealt with as previously recommended

Parts now examined:

(C.S. Items only)

Note:-

To complete the Main Boiler Survey, the Starboard boiler remains to be examined under steam and its safety valves adjusted and the oil burning arrangements and remote controls remain to be examined under working conditions.

W. Ward
Engineer Surveyor to Lloyd's Register
(W. WARD).

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002846-002852-0216