

BY AIR MAIL

2

5th November, 1957.

Two

SINGAPORE.

12179,95,96,99,200,05,09,14,16,21,37 - As recommended.

RMC. 12213 - As recommended.

12137 "ERINNA" - As recommended. The class of the machinery of this ship is subject to lighting and fan circuits in the midship accommodation being altered to conform with Rule requirements at the earliest opportunity. In view of the length of time which has elapsed since the above condition of class was recorded, and the fact that the Owners stated that the matter would be dealt with at the Special Survey, I shall be glad if you will ascertain and let me know what action the Owners propose taking in this respect. I would point out that a fresh record of Continuous Survey was assigned following the survey in June, 1957.

NG" 12201 - As recommended.

SORONG.

36 - As recommended.



© 2020

Lloyd's Register
Foundation