

WRECK
SECTION

No.

" K E R R Y M O R E "

SPECIAL SURVEY (C) becomes due 10.58.


The Glasgow Surveyors report this ship examined afloat and in drydock for damage caused by grounding and found the keel and bottom shell set up and buckled in local areas (p & s) and damage to the internal structure in way.

The Owners have announced their intention to sell this ship for scrap and the ship subsequently proceeded to Troon.

The Glasgow Committee have recommended "To be broken up".

IT IS SUBMITTED the Glasgow Committee's Minute be confirmed.

INSERT IN R.B.
To be broken up.



© 2020

Lloyd's Register
Foundation

002858-002869-0128